

Portable Appliance Test Results

Premises: RPC Limited, 62 High Street, Horsham. RH34 3EW

Engineer: J Clelland

Date: 19th April 2004

Tester: Megger PAT4DV - 9008066

Asset Number	Description	Location	Class 1/2	Freq. Months	Visual Check	Earth Bond (Ω)	Insulation ($M\Omega$)	Polarity	M/W Emmission mW/cm ²	Fuse	Pass / Fail	Comments
B101791	Vacuum cleaner	1st Floor R107	2	12	ok		>50	~		13	Pass	
B101792	Cigarette machine	1st Floor R107	1	12	ok	0.076	>50	ok		13	Pass	
B101793	Glass washer	1st Floor R107	1	12	ok	0.065	>50	ok		13	Pass	Plug replaced
B101794	AC adaptor	1st Floor R107	1	12	ok	0.059	>50	ok			Pass	
B101795	AC adaptor lead	1st Floor R107	1	12	ok	0.072	>50	ok		5	Pass	
B101796	AC adaptor	1st Floor R107	2	12	ok		>50	~			Pass	
B101797	4-way extension	1st Floor R107	1	12	ok	0.056	>50	ok		13	Pass	
B101798	Amplifier	1st Floor R107	2	12	ok		>50	~		5	Pass	
B101799	Amplifier	1st Floor R107	2	12	ok		>50	ok		5	Pass	
B101800	Tuner	1st Floor R107	2	12	ok		>50	ok		3	Pass	Fuse replaced
B101801	AC adaptor	1st Floor R107	2	12	ok		>50	~			Pass	
B101802	Microwave	1st Floor R107	1	12	ok	0.073	>50	~	0.3	13	Pass	
B101803	Fridge	1st Floor R107	1	12	ok	0.121	>50	ok		13	Pass	
B101804	Fridge	1st Floor R107	1	12	ok	0.076	>50	ok		13	Pass	
B101805	AC adaptor	2nd Floor R212	2	12	ok		>50	~			Pass	
B101806	2-way extension	2nd Floor R212	1	12	ok	0.068	>50	ok		13	Pass	
B101807	Fridge	2nd Floor R212	1	12	ok	~	>50	ok		13	FAIL	Not Earthed
B101808	Desk fan	2nd Floor R212	1	12	ok	0.080	>50	ok		3	Pass	
B101809	Spotlight	2nd Floor R212	1	12	ok	0.091	>50	ok		3	Pass	
B101810	Monitor	2nd Floor R212	1	12	ok	0.104	>50	~			Pass	